



COMPREHENSIVE VEHICLE INSPECTION REPORT

300+ CHECKPOINT INSPECTION
Photo-Evidence Based • Professional Digital Report

Inspection ID CPM-DEMO-001	Inspection Date 14 September 2026	Inspection Type New Car PDI
Customer Demo Customer	Vehicle Hyundai Creta	Variant SX (Demo)
Registration DL 01 AA 0000	Odometer 125 km	Inspector CAR PDI MASTERS Inspector

OVERALL RESULT	SAMPLE SCORE	EVIDENCE
286 / 300+ Demo scenario summary	92 / 100	Photo-supported Sample pages include illustrative vehicle photos. Final reports will use actual inspector-captured evidence.

INSPECT • VERIFY • DRIVE WITH CONFIDENCE
A transparent inspection report built around checkpoint results, observations and relevant photo evidence.

SAMPLE / DEMO DOCUMENT: The vehicle photos in this sample are illustrative and are included to demonstrate how evidence will appear in a real customer report.



01 • PHOTO-EVIDENCE INSPECTION APPROACH

The report is designed to make the inspection transparent: customers can see the vehicle overview, understand checkpoint results and review photographic evidence for relevant areas and findings.

300+ CHECKPOINTS Detailed inspection across exterior, paint, glass, electrical, interior, mechanical, tyres, suspension, AC, safety and delivery checks.	PHOTO PROOF Important inspection areas and findings are supported by photos captured during the actual inspection.	CLEAR RESULT OK • ATTENTION • NOT OK • N/A with observations and recommendations.
--	--	---

Evidence principle: **Checkpoint** → **Result** → **Observation** → **Photo Evidence** wherever photographic evidence is relevant.

02 • VEHICLE PHOTO EVIDENCE — SAMPLE VIEW

This page shows how a real customer report can visually document the inspected vehicle from multiple angles and key areas. **Photos below are illustrative demo images.**



Front View • [SAMPLE PHOTO](#)



Rear View • [SAMPLE PHOTO](#)



LHS Side View • [SAMPLE PHOTO](#)



RHS Side View • [SAMPLE PHOTO](#)



Interior Dashboard • [SAMPLE PHOTO](#)



Engine Bay • [SAMPLE PHOTO](#)

In the production report, these sample images will be replaced by photographs captured by the inspector during the actual PDI.

03 • KEY FINDINGS WITH PHOTO EVIDENCE

01 Front / Exterior

Checkpoint: Front bumper condition

Status: ATTENTION

Observation: Minor cosmetic mark represented in this demo. Final report will show the actual observed condition and recommendation.

Recommendation: Record rectification/re-check where applicable.



02 Exterior / Side

Checkpoint: Panel & alignment

Status: OK

Observation: Side profile represented as visually acceptable in this demo.

Recommendation: Record rectification/re-check where applicable.



03 Interior

Checkpoint: Dashboard & controls

Status: OK

Observation: Interior dashboard and visible controls represented as checked in this demo.

Recommendation: Record rectification/re-check where applicable.



04 Engine Bay

Checkpoint: Visible condition

Status: OK

Observation: Engine bay shown for visual documentation only in this demo.

Recommendation: Record rectification/re-check where applicable.



04 • 300+ POINT INSPECTION SUMMARY

Category	Checkpoints	OK	Attention	Not OK
Exterior & Body	60+	58	2	0
Paint & Panel	40+	39	1	0
Lights & Electrical	35+	35	0	0
Tyres, Wheels & Brakes	35+	34	1	0
Interior & Features	40+	40	0	0
Engine & Transmission	35+	34	1	0
Suspension, Steering & Undercarriage	30+	29	1	0
AC & Climate Control	20+	20	0	0
Safety & Warning Systems	20+	20	0	0
Documents / Delivery Checks	15+	15	0	0

Important: The live system must contain 300+ distinct meaningful checkpoints before this claim is used commercially.

05 • REPRESENTATIVE CHECKPOINT LOG

Section	Checkpoint	Result	Evidence / Remark
Exterior	Front bumper condition	ATTENTION	Front View • Sample Photo
Exterior	Bonnet alignment	OK	Front View • Sample Photo
Exterior	LHS side profile	OK	LHS View • Sample Photo
Exterior	RHS side profile	OK	RHS View • Sample Photo
Electrical	Dashboard / infotainment	OK	Interior • Sample Photo
Engine	Engine bay condition	OK	Engine Bay • Sample Photo
Tyres	Wheel / tyre visual	OK	Photo evidence captured in live report
Delivery	Toolkit / jack / stepney	OK	Physical verification in live inspection



06 • FINAL CUSTOMER SUMMARY

OVERALL CONDITION	92 / 100
Attention item Demo cosmetic observation only.	Critical issues 0 in this demo scenario.
Recommended action Rectify noted item and re-check where applicable.	Decision Customer decides after reviewing report.

07 • SCOPE & IMPORTANT LIMITATIONS

- Inspection is a visual and functional assessment performed at the stated inspection location and time.
- Non-invasive inspection cannot guarantee hidden/internal components that cannot reasonably be accessed.
- Findings reflect the vehicle condition observed during inspection and are not a warranty or guarantee of future performance.
- Road-test and diagnostic observations depend on access, vehicle condition, permissions and available equipment.
- Document verification should clearly state what was actually checked.
- The report should not claim an issue is absent merely because it was not observable during inspection.

CAR PDI MASTERS

Inspect • Verify • Drive With Confidence

SAMPLE / DEMO DOCUMENT — Vehicle photos shown in this report are illustrative sample images, not real customer inspection evidence.